

CEM26/GEM28 Firmware Upgrade History

V20210422 Firmware Upgrade

Bug Fixed:

- Star alignment results not recorded in hand controller

This version needs Upgrade Utility V2.23 and later

V20210105 Firmware Upgrade

Added Function:

- Support iOptron electronic focuser

Improved:

- Meridian limit increased to 20 degree
- Will memorize MAX slew speed when power off the mount

This version needs iOptron Commander 6.4

This version needs Upgrade Utility V2.11 and later

V20201030 Initial Release