

SkyHunter Firmware Upgrade History

V20220510 SkyHunter Main Board Firmware Upgrade

Bug Fix:

- Fixed tracking speed issue
- Improved autoguiding performance

V20220301 Initial Release: 8410 Hand Controller

V20220305 Initial Release: SkyHunter Main Board