

CEM70 Firmware Upgrade History

FW230305 Firmware package upgrade for **mount** and **8410** hand controller
Main: V230305, RA: 220120, DEC: 220120, 8410HC: V220301

Bug fixed:

- Minor bug related to GPS display.

FW220301 Firmware package upgrade for **mount** and **8410** hand controller
Main: V220120, RA: 220120, DEC: 220120, 8410HC: V220301

New Features:

- Added CEM70EC2 mount.

V210105 Mount firmware package upgrade

V210105 Hand controller firmware upgrade

Changes:

- Now the mount needs iOptron Commander 6.4.0.0 and above for computer control
- iOptron Upgrade Utility V2.11 or above is needed

New Features:

- Added Maximum Slew Rate and other iOptron Commander related functions

V200120 Initial Release: CEM70EC mount firmware package

V200116 Initial Release: mount firmware package

V200303 Initial Release: hand controller